Ōwhiro Bay Coastal Engineering Options Assessment

Prepared for:

Absolutely Positively Wellington City Council Me Heke Ki Pôneke



MOHIO - AUAHA - TAUTOKO <u>UNDERSTAND - INNOVATE - SUSTAIN</u>

PO Box 151, Raglan 3225, New Zealand Ph: +64 7 825 0087 | info@ecoast.co.nz | www.ecoast.co.nz

Ōwhiro Bay Coastal Engineering Options Assessment

Report Status

Version	Date	Status	Approved by
V. 1	11 March 2021	Final Draft	RM

It is the responsibility of the reader to verify the version number of this report.

Authors

Shaw Mead BSc, MSc (Hons) and PhD

The information contained in this document, including the intellectual property, is confidential and propriety to Ecological and Physical Coastal Consultants Limited (T/A eCoast). It may be used by the persons to whom it is provided for the stated purpose for which it is provided, and must not be imparted to any third person without prior written approval from eCoast. eCoast reserves all legal rights and remedies in relation to any infringement of its right in respects of its confidential information. eCoast© 2021



Contents

С	ontent	S	. i
F	igures		.ii
Т	ables.		iv
1	Bad	ckground	5
2	Phy	vsical Setting	8
	2.1	Wave Climate	9
	2.2	Tides1	1
	2.3	Topography/Bathymetry1	1
	2.4	Historical Imagery1	3
3	Clir	mate Change (CC) and Sea Level Rise (SLR)1	5
4	The	e 15 th April 2020 Extreme Over-Topping Event 1	7
	4.1	Over-Topping in Extreme Events 1	7
	4.2	Components of the 15 April 2020 event 1	8
	4.3	April versus July Extreme Events1	9
5	Ōw	hiro Bay Residents Association Coastal Survey2	21
6	Opt	tions Assessment	23
	6.1	Monitoring2	23
	6.2	Do Nothing2	27
	6.3	Beach Management: Reduction of the Berm Height2	27
	6.4	Dune Planting Stabilisation	28
	6.5	Protect with Seawalls and Revetments	30
	6.6	Creation of Buffers	33
	6.7	Managed Advance/Buy Time – Offshore Structures	35
	6.8	Hybrid Solutions – Management and Forecasting and Structures	37
	6.9	Retreat	37
7	Ree	commendations	38
	7.1	Short Term Management	38



7.1.1	Monitoring System	38
7.1.2	Beach Grading	38
7.1.3	Improvement of Forecast/Warning System	39
7.2 M	edium Term Management	39
7.2.1	Revetment Construction	39
7.2.2	Buffer Zones/Coastal Vegetation	40
7.3 Lo	ong Term Management	40
Reference	S	43
Appendix A	A – Historical Imagery	45
Appendix E	3 – Ōwhiro Bay Residents Association Coastal Survey	53
Appendix (C – Remote Video Monitoring System	54

Figures

Figure 1.1. Extreme over-topping at Ōwhiro Bay on 15 th April 20205
Figure 1.2. Community engagement is a fundamental component for the development of
successful coastal protection and adaptation and corresponds to many of the elements
required to secure and implement a long-term strategic planning and decision-making
framework for coastal areas potentially, or already, affected by coastal hazards and climate
change effects, such as sea-level rise. (Source: MfE, 2017. Coastal Hazards and Climate
Change: Guidance for Local Government)
Figure 2.1. Location of Ōwhiro Bay8
Figure 2.2. $\bar{O}\mbox{whiro}$ Bay is a shingle pocket beach with platform reefs along the eastern and
western sides and is constrained by seawalls and a coastal road around the entire bay (Figure
2.1)
Figure 2.3. Wave roses of significant wave height (Hs) and peak period (Tp) for the location
shown (42 S, 175 E) 10
Figure 2.4. Tides in Wellington Harbour (top), which the tide tables are based on (Table 2.2),
have a larger range than tides on the open coast at Ōwhiro Bay (bottom)
Figure 2.5. LiDAR topography of $\bar{O}whiro$ Bay. Top) Contours from zero (red) in 5 m
increments. Bottom) The embayment levels from zero (mean sea level) to 5 m high; note the
lowest area in the NW of the bay 12
Figure 2.6. Ōwhiro Bay is a relatively shallow and narrow embayment, which is 8-9 m deep
at the entrance, shoaling to 2 m deep at the head of the bay

Figure 2.7. Replacement of the circa 1930's mortared brick seawall on the eastern side of Figure 3.1. Four scenarios of New Zealand-wide regional sea level rise projections to 2150 Figure 3.2. Based on RCP 8.5, in 30 years' time, extreme water levels with a now day 1 in 200 year return period could have a 1 in 2.5 year return period. The sea level is projected to rise 0.3 m in the next 30 years (blue arrow). At present, a 1 in 200 year return period event results in an extreme water level 0.3 m higher than the usual mean level of the sea (amber arrows). With an addition of 0.3 m water level, the same extreme water level that occurs once Figure 4.1. The metocean components that lead to wave over-topping in extreme events. 17 Figure 4.2. Significant wave height (top) and peak wave period (bottom) at the extraction location for the April 15, 2020 event at Ōwhiro Bay. The date marks are in UTC, which means they are at noon NZST, meaning that the peak of the event coincided with the noon high tide, allowing for approximately 1 hour for 14.7 second period waves to propagate from the extraction location (these waves were moving at ~20 m/s over a distance of ~ 70 km - Figure Figure 6.2. Over-topping example images at Manu Bay breakwater, Raglan, taken from the 11th April 2019 at high tide during inclement conditions (multi-direction incident swells, Figure 6.3. Rectification of the Whaingaroa Bar to determine breaker locations and sand bars Figure 6.4. (Top) Ōwhiro Bay is well suited to remote video monitoring due to the elevated topography. (Middle) There are several potential powered sites on the eastern side of the bay, (Bottom) as well as the option for a remote system on the top hill country on the western Figure 6.5. Results from the Overtopping Neural Network calculator simulations from (Top) 40 to 70 Ōwhiro Bay Parade where there is no reef platform and from (Bottom) 80 to 92 Ōwhiro Bay Parade where there is a reef platform present, for present day and with 0.5 m of SLR.28 Figure 6.6. Dune planting has significantly increased the width of the dune buffer zone at Lyall Figure 6.7. Left) Dune stabilization at Island Bay, and Right) the gravel beach at Ōwhiro Bay.

Figure 6.8. Top Left) The re-curved wall at Island Bay. Both Left and Right) The seawall and revetment along the Esplanade near the Victoria University Coastal Ecology Laboratory... 30



Figure 6.9. The shingle beach is presently almost level with the footpath on the eastern side
of the bay where some of the worst over-topping occurred in April 2020
Figure 6.10. Waves at the beach during the 15 April 2020 extreme event
Figure 6.11. Potential rock revetment for Ōwhiro Bay to reduce wave run-up onto the road
and threatening properties during extreme events
Figure 6.12. A buffer zone of coastal plants along The Esplanade. At Ōwhiro Bay it is
envisaged that there would be a lower wall/planting above a graded berm as to reduce any
impact on views across the bay
Figure 6.13. Potential planted buffer zone above graded berm to reduce/prevent extreme
over-topping
Figure 6.14. The submerged reef at Oriental Bay is designed to maintain beach sand along
the eastern part of the beach through wave rotation (Mead and Black, 2001).
(https://satellites.pro/New_Zealand_map#-41.290467,174.795637,19)
Figure 6.15. Waves breaking before entering Ōwhiro Bay on 15 April 2020. As can be seen
in Figure 2.6, the entrance to $\bar{O}whiro$ Bay is relatively shallow, and so with the application of
the rule of thumb depth to wave height at breaking ratio of 0.78, a 6.7 m wave (i.e., the peak
significant wave height) will break in 8.6 m of water, with the largest waves of the 15 April
event likely breaking in water depths of ~15 m
Figure 7.1. Options to reduce or prevent over-topping at Ōwhiro Bay. The immediate
recommendations include establishing a monitoring system (red star) and beach grading
(orange lines). Medium term management could include upgrade and extension of the rock
revetment (blue line) and the creation of buffer zones (green line). In the longer term, there is
potential that submerged breakwaters could be beneficial, although the efficacy, size and
location of these is presently unknown

Tables

Table 2.1. Return period wave heights	10
Table 2.2. Tidal ranges for Wellington. Elevations refer to chart datum	11
Table 3.1. Comparison of metocean components during the extreme over-topping event	on
15 April 2020 and the warning date of 1 July 2020	19



1 Background

Ōwhiro Bay is vulnerable to over-topping during storm events. On 15th April 2020, a particular extreme event occurred (discussed in Section 3 of this report), which resulted in extensive damage and the commissioning of this investigation into coastal engineering options to address the over-topping hazard by the Wellington City Council.



Figure 1.1. Extreme over-topping at Ōwhiro Bay on 15th April 2020.

The process undertaken to consider engineering options to mitigate the over-topping hazard at Ōwhiro Bay was similar to that undertaken at Lyall Bay in 2016 (Mead and Phillips, 2016), although more focussed and at a smaller scale. The approach was a compressed MfE (2017) methodology that follows the 10-step decision cycle where community engagement is central to the process (Figure 1.2).





The 10-step decision cycle, grouped around five questions

Figure 1.2. Community engagement is a fundamental component for the development of successful coastal protection and adaptation and corresponds to many of the elements required to secure and implement a long-term strategic planning and decision-making framework for coastal areas potentially, or already, affected by coastal hazards and climate change effects, such as sea-level rise. (Source: MfE, 2017. Coastal Hazards and Climate Change: Guidance for Local Government).

The project included the following steps:

- 1. Initial Stakeholder Consultation and Site Visit. Due to Covid-19 and the second Auckland lock-down (mid-August), the initial stakeholder meeting was undertaken remotely as a virtual meeting. This was to go through the issues and the aspects of the bay that are valued by the stakeholders (i.e., Questions 1 and 2 in Figure 1.2). This also included the development of a stakeholder questionnaire to collate detailed information form the stakeholders with respect to values, issues such as over-topping, erosion, etc.. A site inspection of Ōwhiro Bay and the various engineered structures around it was undertaken in late September 2020. The information gained from the initial stakeholder meeting, questionnaire and site visit have been incorporated into the options study to develop a set of viable options to address the issues existing at Ōwhiro Bay
- 2. Collation and review of existing reports, literature and data pertaining to the site. This has included any existing survey data (in order to determine elevations of areas above the beach), historical aerial photography, and a variety of world-wide metocean



datasets (e.g. waves, winds, bathymetry, air pressure, etc), dating back to 1979 and earlier, which is updated each month. eCoast's MDI (Metocean Data Interface) was accessed to provide long-term offshore wave data, regional bathymetry, nautical charts, wind data and tide data. Along with the information collected during the site visit and stakeholder meeting, these data were used to build up an understanding of the physical make-up of the site and the surrounding area, and the coastal hazards that it is subject to.

- Identification and Evaluation of Options. A range of options were then developed based on the results of 1 and 2 above, that is, options that are viable for the location. Each option was then evaluated with respect to its applicability and the pros and cons (Question 3 of Figure 1.2).
- 4. Stakeholder Presentation. The options evaluation then presented back to the stakeholders at Ōwhiro Bay on 21 February 2020, including recommendations on the best options to apply for this location. This provided further stakeholder input, and an opportunity to answer questions on the options
- 5. *Reporting, graphics and specifications*. This report includes concise descriptions of all of the above tasks and recommended implementation plan and monitoring/adaptive management (i.e. Questions 4 and 5 of Figure 1.2).



2 Physical Setting

Ōwhiro Bay is a relatively small embayment on Wellington's south coast (Figure 2.1). Enclosed by steep headlands either side, the small sandy pocket beach faces south-southwest and is backed by the coastal road. The coast here is characterised by an uplifted, eroding rock platform reefs and shingle beach, and is considered an exposed and energetic environment due to its exposure to large Southern Ocean swells.



Figure 2.1. Location of Ōwhiro Bay.

Comprising the western limit of Wellington's residential south coast, the shoreline is developed around the bay with the most significant modification being the road and its associated seaward protection structures above the shingle beach (Figure 2.2).





Figure 2.2. Ōwhiro Bay is a shingle pocket beach with platform reefs along the eastern and western sides and is constrained by seawalls and a coastal road around the entire bay (Figure 2.1).

The geomorphology of the region is typical of a shore platform that has developed along an actively uplifting coastline, with the most recent abrupt uplift event being the 1855 AD earthquake (MM 8.1 - 8.2) associated with the Wairarapa Fault to the east of Wellington Harbour. This thrusted the peninsula upward by about 1.5 m and contributed to an overall uplift of 8 m (± 1 m) since 6500 BP (Pillans and Huber, 1995). Thickly bedded, Late Triassic Greywacke dominates the geology of the region. The rocks are medium to coarse grained quartzofeldspathic sandstone, occasionally interbedded with argiillite and all dip steeply to the west (Kennedy and Beban, 2005).

2.1 Wave Climate

A long-term time series of wave conditions dating back to 1979 was extracted from the National Oceanic and Atmospheric Administration Wave Watch 3 (NOAA WW3) global wave model. The Ōwhiro Bay offshore wave climate is summarised in the wave roses in Figure 2.3.





Figure 2.3. Wave roses of significant wave height (Hs) and peak period (Tp) for the location shown (42 S, 175 E).

A statistical analysis was carried out on the time series of wave heights in a directional bin from the southeast to southwest (i.e. the directions from which waves can approach Ōwhiro Bay, >140° and <210°). An extreme value analysis was carried out using the WAFO (2011) toolbox developed by faculty of Engineering, Mathematical Statistics, Lund University, Sweden, which is a commonly used statistical toolbox for carrying out univariate extreme value analysis. The routines in WAFO were used for fitting a statistical distribution to the occurrence of wave heights. The analysis was carried out using a Peaks over Threshold (PoT) method and fitting the resultant data to a generalised Pareto distribution. A threshold of 6.5 m was used to determine extreme events. The fitted distributions were used to estimate the value of the various return period events which are shown in Table 2.1.

Return Period (yrs)	1	5	10	30	50	100
Wave Height (m)	6.51	7.55	8.02	8.78	9.15	9.66

Table 2.1. Return period wave heights.



2.2 Tides

The spring tidal range for Wellington Harbour is \sim 1.4 m (Table 2.2). However, Tides in Wellington Harbour have a larger range than tides on the open coast at Ōwhiro Bay (Figure 2.4).

Table 2.2.	Tidal ı	ranges for W	ellington.	Elevations	refe	er to chart da	atum.

MHWS	MHWN	MLWN	MLWS	MSL
1.8	1.4	0.7	0.4	1.13



Figure 2.4. Tides in Wellington Harbour (top), which the tide tables are based on (Table 2.2), have a larger range than tides on the open coast at Ōwhiro Bay (bottom).

2.3 Topography/Bathymetry

Ōwhiro Bay has very steep topography with an intertidal rocky shore platform (Figure 2.5). The embayment is constrained by steep cliffs from ~5 m above mean sea level (MSL), with the fringing road being at 3-4 m above MSL, except in the NW corner of the bay (Figure 2.5)





Figure 2.5. LiDAR topography of Ōwhiro Bay. Top) Contours from zero (red) in 5 m increments. Bottom) The embayment levels from zero (mean sea level) to 5 m high; note the lowest area in the NW of the bay.

The nautical chart of Ōwhiro Bay shows that it is a relatively shallow and narrow embayment, which is 8-9 m deep at the entrance, shoaling to 2 m deep at the head of the bay (Figure 2.6).





Figure 2.6. Ōwhiro Bay is a relatively shallow and narrow embayment, which is 8-9 m deep at the entrance, shoaling to 2 m deep at the head of the bay.

2.4 Historical Imagery

Appendix A contains a suite of historical aerial imagery of \bar{O} whiro Bay dating back to 1938. The rocky shore has remained very stable in this period, with the road in the same location as it was in 1938 and the main changes being the increased housing and other buildings around the embayment. As noted on the WCC website, in 2010, the Council identified structural deficiencies in the 159 metre length sea wall – a circa 1930's mortared brick structure – on [the eastern side of] \bar{O} whiro Bay Parade, and initiated a programme to replace the entire length (which is nearing completion Figure 2.7).





Figure 2.7. Replacement of the circa 1930's mortared brick seawall on the eastern side of Ōwhiro Bay.



3 Climate Change (CC) and Sea Level Rise (SLR)

Figure 3.1 illustrates four scenarios of New Zealand-wide regional sea level rise (SLR) to the year 2150 from the IPCC AR5 cited in MfE (2017), which is being driven by climate change (CC)/global warming. The most extreme scenario (NZ RCP¹ 8.5 H+) indicates that in 100 years the sea level will rise by 1.34 m with the medium projections indicating SLR values in 100 years of 0.55, 0.67, 1.06 m for RCP2.6 m, RCP4.5 m and RCP8.5 m, respectively. The projections include a New Zealand-wide regional offset, with a small additional SLR above the global mean projections. For more information on RCPs refer to MfE (2017), Tables 10 and 11.



Figure 3.1. Four scenarios of New Zealand-wide regional sea level rise projections to 2150 based on Kopp *et al.* (2014) cited in MfE (2017).

The four sea-level rise scenarios are based around three RCPs (RCP2.6, RCP4.5 and RCP8.5). Three of the scenarios are derived from the median projections of global sea-level rise for the RCPs presented by the IPCC in its Fifth Assessment Report (AR5) (Church et al, 2013). These have been extended to 2120, to meet the minimum requirement of assessing

¹ RCP refers to representative concentration pathways, which are scenarios based on how human CO₂ emissions will change in the future, with RCP 8.5 being 'business as usual' and continued increasing consumption.



risk over at least 100 years, as required by the NZCPS 2010. A further extension to 2150, using the rates of rise from Kopp *et al.* (2014), provides a longer view over 130 years (with a gap shown in Figure 3.1 between the two sets of projections). It is also a reminder that sea level will keep rising after 100 years, irrespective of actual future greenhouse gas emissions (MfE, 2017).

While there is still uncertainty around projected SLR rates, we can get some indication on how it will impact on extreme events. For example, based on RCP 8.5, in 30 years' time extreme water levels with a present day 1 in 200 year return period could have a 1 in 2.5 year return period. This is demonstrated in Figure 3.2, where the sea level is projected to rise 0.3 m in the next 30 years. At present, a 1 in 200 year return period event results in an extreme water level 0.3 m higher than the usual mean level of the sea (Figure 3.2). With an addition of 0.3 m water level, the same extreme water level that occurs once every 200 years on average will occur every 2.5 years on average (Figure 3.2). Therefore, over-topping events at Ōwhiro Bay are expected to occur more frequently and be more extreme with SLR.



Figure 3.2. Based on RCP 8.5, in 30 years' time, extreme water levels with a now day 1 in 200 year return period could have a 1 in 2.5 year return period. The sea level is projected to rise 0.3 m in the next 30 years (blue arrow). At present, a 1 in 200 year return period event results in an extreme water level 0.3 m higher than the usual mean level of the sea (amber arrows). With an addition of 0.3 m water level, the same extreme water level that occurs once every 200 years on average will occur every 2.5 years on average (red arrows).



4 The 15th April 2020 Extreme Over-Topping Event

To provide some insight into what drove the extreme over-topping event on 15th April 2020, the various metocean components were analysed. In addition, this event was compared to the 1 July 2020 event, when due to the extreme event in April a wave warning system was brought in to alert councils and civil defence and residents were warned to prepare in case they need to evacuate their homes ("Ōwhiro Bay residents warned to be ready to evacuate"²). However, extreme over-topping did not occur on 1 July.

4.1 Over-Topping in Extreme Events

Over-topping at Ōwhiro Bay occurs during extreme events when a series of factors occur coincidentally. That is, a combination of:

- High tide (spring or King tides will exacerbate the event);
- Storm surge due to low atmospheric pressure (1 cm of increased water level for every millibar below average pressure);
- Onshore winds causing wind set-up;
- Wave set-up, with longer period waves increasing the amount of set-up, and;
- Large waves.

When these factors all occur at the same time, the potential for over-topping is increased (Figure 4.1).



Figure 4.1. The metocean components that lead to wave over-topping in extreme events.

² https://www.rnz.co.nz/news/national/420286/owhiro-bay-residents-warned-to-be-ready-to-evacuate.



4.2 Components of the 15 April 2020 event

Large waves washed over the road at Ōwhiro Bay on 15/04/2020 leading to one hospitalisation, several evacuations and damage to property. The offshore wave conditions during this event can be seen in Figure 4.2 below. The peak was 6.71 m at 14.7 seconds at 11:00 at the hindcast offshore extraction site (Figure 2.3), which results in the peak of the event reaching Ōwhiro Bay at approximately noon.



Figure 4.2. Significant wave height (top) and peak wave period (bottom) at the extraction location for the April 15, 2020 event at Ōwhiro Bay. The date marks are in UTC, which means they are at noon NZST, meaning that the peak of the event coincided with the noon high tide, allowing for approximately 1 hour for 14.7 second period waves to propagate from the extraction location (these waves were moving at ~20 m/s over a distance of ~ 70 km - Figure 2.3).

Barometric pressure was approximately 8 millibars below average, resulting in some 8 cm of increased water level above the predicted tide level (Figure 4.3). High tide of 1.8 m also occurred at noon; i.e. the same time as the peak of the event occurred in Ōwhiro Bay. An onshore southerly wind of 25-30 kmph was blowing at noon on 15th April.



Figure 4.3. Barometric pressure data from Wellington airport.

Although the swell on 15th July 2020 peaked at only 0.2 m above the annual return period wave height (Table 2.1), it had a long period of 14.7 seconds, which is not usual for the south coast of Wellington³, and as noted above, the longer the period, the higher the water level due to wave set-up. The onshore winds, lower than average barometric pressure, and a spring tide all coincided with the peak of the 6.7 m swell arriving at the bay at noon. This resulted in the 'perfect storm' for an extreme over-topping event.

4.3 April versus July Extreme Events

As noted above, a large south swell was forecast to arrive on 1 July 2020 by the wave warning system, just a couple of months after the extreme event of 15 April 2020. It is unknown if any over-topping occurred due to the second event, partly since it occurred in the middle of the night, however, it is known that the extreme over-topping and damage associated with the April event did not occur. The various metocean components for the 2 events are presented in Table 4.1.

	15-Apr-20	1-Jul-20
Hs (significant wave height) (m)	6.71	6.42
Tp (peak wave period) (seconds)	14.7	11.32
Direction (degrees true)	199.8	195.1
Peak time	1200	2400
High tide time	1200	0200
High tide level (m)	1.8	1.7
Barometric pressure	1005	1004
Wind speed (kmph)	22	18.5
Wind direction (degrees true)	190	214

Table 4.1. Comparison of metocean components during the extreme over-topping event on 15 April 2020 and
the warning date of 1 July 2020.

Comparison of the events in Table 4.1 indicates that although the wave heights were relatively similar (the July event was some 0.29 m smaller), the tide was of a similar height (0.1 m smaller in July), and the swell was from a similar direction, the wave periods and timings of the event were quite different. The wave period in April was some 3.4 seconds longer resulting in increased wave set-up (Figure 4.1), and the peak of the event coincided with the time of the

³ The mean wave height a period for the Wellington South Coast is 1.2 m at 9 seconds (Mead and Phillips, 2016).



high tide, while it was 2 hours later in July. They were not 'freak waves'⁴ rather a coincident combination of parameters that resulted in an extreme over-topping event.

The important point to realise from this comparison is that it is the combination of factors that result in the extremity of an over-topping event in Ōwhiro Bay (indeed in any location), and so a warning system must consider all the parameters of a potential over-topping event and not only the predicted size of the waves. A warning system in order to allow residents to prepare for events will be an important management system going forwards, since these events will occur more frequently due to sea level rise (SLR). Along with utilising a range of metocean statistics to develop a reliable warning system, a remote monitoring system can also greatly improve a warning system's reliability by recording extreme over-topping events so that the metocean conditions that lead to the events can be incorporated into the predictive parameters for warnings.

⁴ Freak or rogue waves are single unusually large, unpredictable and suddenly appearing surface waves that can be extremely dangerous to ships, even to large ones.



5 Ōwhiro Bay Residents Association Coastal Survey

Due to Covid-19 and the second Auckland lock-down (mid-August 2020), the initial stakeholder meeting was undertaken remotely as a virtual meeting to go through the issues and the aspects of the bay that are valued by the stakeholders and provide insight to over-topping events. This also included the development of a stakeholder questionnaire to collate detailed information form the stakeholders with respect to values of the area, issues such as over-topping, erosion, etc.. The survey and results are attached as Appendix B, and are summarised here stating the general trends in the responses:

- 1. There were 51 respondents.
- Does over-topping occur at your property?
 34 residents responded Yes
- How often does it occur?
 Infrequently, it only happens when there is a significant weather or wave event
- 4. When wave topping does occur what is your most frequent experience? Varying degrees of inundation
- How frequently are you using the South Coast area and what do you use it for? Daily I use it every day – wide range of uses.
- 6. What's important to you?

A wide and varied ranged of responses from safety to recreation to the environmental values.

- 7. What changes have you observed?
 - Erosion and movements of the beach
 - Gravel ramping
 - Loss of vegetation in some areas, growth in others
 - Damage to structures:
 - o Footpaths
 - o Bridge
 - o Safety barriers
 - o Vehicles
 - o Carpark
 - o etc., etc.
- 8. Acceptability of Potential Options:
 - Natural defences Yes

Beach/gravel management - Yes

Groynes – Mixed views



Seawalls – mostly Yes, some No Loss of coastal footpath – No⁵ Loss of coastal parking – Yes/Neutral Reduce to one lane – Mixed Views Homeowner self-protection – Mixed Views Offshore breakwater(s) – Yes Do nothing – No (unanimous)

While it is clear that at some point in the future retreat is inevitable due to SLR, a general sentiment is:

"I am willing to have some fairly major changes in order for us to safely live here in the decades to come."



⁵ Note, during the final stakeholder meeting it was conveyed that as long as there was a footpath on one side of the road, then loss of some footpath to make space for structural responses would be acceptable.



6 **Options Assessment**

A range of options were developed based on the results of the investigations described above, that is, options that are viable for the location. The options evaluation was presented to the Ōwhiro Bay Residents Association on 21 February 2020 at Ōwhiro Bay School. The following options were considered and discussed:

- 1. Do Nothing.
- 2. Beach Management: Reduce the Berm Height.
- 3. Dune Planting Stabilisation
- 4. Protect with Seawalls.
- 5. Create Buffers.
- 6. Advance/Buy Time Offshore Structures.
- 7. Hybrid Solution Structures and Management and Forecasting.
- 8. Retreat When?

6.1 Monitoring

In order to better understand the combination of metocean parameters that lead to extreme over-topping events at Ōwhiro Bay, as well as to ascertain the efficacy of any implemented interventions and adaptively manage the responses, a critical component of the strategy is monitoring. Monitoring comes in many forms, with more sophisticated and cost-effective methodologies being developed in recent years. Given the kind of information that requires monitoring at Ōwhiro Bay (i.e., over-topping events, movement of shingle around the beach, efficacy of options to mitigate the over-topping, etc), remote video monitoring is likely the most efficient and cost-effective methodology.

Figure 6.1 shows a remote monitoring camera set-up that is being used to monitor the surf breaks at Lyall Bay; eCoast has a network of cameras for this purpose (Atkin *et al.*, 2017), and a similar unit is being used to monitor over-topping of the breakwater at Manu Bay boatramp, which is a health and safety issue (Mead, 2020). In these cases, the systems are connected to a domestic power supply, although solar powered units can be used where the electricity grid is not available.

The monitoring records can be set-up to capture at any frequency, interval and the house micro-processor can undertake a variety of statistical analyses before saving the data to the Cloud for security. To consider over-topping at Ōwhiro Bay, a set-up that records a 20 minute block of images every 1 hour (1,200 images at 1 Hz) during daylight hours, with continuous



20 min blocks for an hour either side of high tide is a potential monitoring set-up. Each cube is time-stacked and mean, minimum and maximum events are determined (via colour recognition) and are sent to the Cloud with images. These data can then be post-processed in a number of ways to consider the locations and extent of over-topping, the level of beach material around the bay, etc., including rectification of the images to provide a 'bird's-eye' view of the bay (Figure 6.3). Appendix C provides a detailed description of the camera system.



Figure 6.1. A remote monitoring camera installation at Lyall Bay (Atkin et al., 2017).



Figure 6.2. Over-topping example images at Manu Bay breakwater, Raglan, taken from the 11th April 2019 at high tide during inclement conditions (multi-direction incident swells, northerly winds, low pressure) (Mead, 2020).





Figure 6.3. Rectification of the Whaingaroa Bar to determine breaker locations and sand bars (Harrison and Bryan, 2014)

Ōwhiro Bay, and indeed much of the southern Wellington coast, is well suited to remote video monitoring due to the elevated topography (e.g. Figure 2.5). There are several potential powered sites on the eastern side of the bay, as well as the option for a remote system on the top hill country on the western side of the bay (Figure 6.4).





Figure 6.4. (Top) Ōwhiro Bay is well suited to remote video monitoring due to the elevated topography. (Middle) There are several potential powered sites on the eastern side of the bay, (Bottom) as well as the option for a remote system on the top hill country on the western side of the bay.



6.2 Do Nothing

'Do nothing' is a traditional option, although given the investigations presented here, and the resounding 'No' to this option from the Ōwhiro Bay Residents Association, this option is not being considered. The outcomes of doing nothing can be related to Section 3 above, that is, over-topping events at Ōwhiro Bay are expected to occur more frequently and be more extreme with SLR.

6.3 Beach Management: Reduction of the Berm Height.

It is understood that the berm height against the seawalls within Ōwhiro Bay was traditionally reduced/removed with a digger by the quarry in order to prevent/reduce over-topping. The specifics of these works are not well-known; e.g. how often (yearly has been put forward), to what depth, in what areas, where was the material removed to, etc? In the absence of verified specifics, and while there are some obvious areas where berm reduction is required (e.g. the north western corner of the bay), monitored trials will provide information on the efficacy of this approach, and guidance on how to modify as required (i.e. adaptive management).

In order to provide some indication that this approach would be of value to reduce over-topping in Ōwhiro Bay, wave run-up and over-topping were considered using the LiDAR data (Figure 2.5) and photographs to approximate the beach slopes. Predictions of mean wave over-topping discharge were undertaken for i) no berm reduction, ii) 1 m of berm reduction, and iii) 2 m of berm reduction using the Overtopping Neural Network calculator developed by Deltares Hydraulics. This prediction tool is underpinned by a dataset of physical model tests and does carry some small inaccuracies due to scale effects, model effects and measurement errors. However, it is considered a robust tool and gives a good estimate of over-topping discharge. Details of the methodology followed, and the development process of this calculator, are described in van Gent *et al.* (2007) and the EuroTop (2007) manual.

Simulations were undertaken from 40 to 70 Ōwhiro Bay Parade where there is no reef platform and from 80 to 92 Ōwhiro Bay Parade where there is a reef platform present, for present day and with 0.5 m of SLR. As can be seen from Figure 6.5, significant reductions in over-topping discharge can be gained by reducing the height of the berm against the seawall, which strongly supports the historical observations.

It is known that the south coast of Wellington is accreting (Carter and Lewis, 1995), and so removal of beach shingle may also become a component of this management option, especially if monitoring demonstrates that the material removed from in front of the seawalls cannot be moved to other parts of the beach without compromising the strategy. However, it



is also known that if the water depth is increased (e.g. by removal of material and/or due to SLR), then higher waves can approach the beach increasing over-topping discharge, and so pushing material down the beach may prove to be a better option.





Figure 6.5. Results from the Overtopping Neural Network calculator simulations from (Top) 40 to 70 Ōwhiro Bay Parade where there is no reef platform and from (Bottom) 80 to 92 Ōwhiro Bay Parade where there is a reef platform present, for present day and with 0.5 m of SLR.

Beach push-ups are used around New Zealand to provide increased coastal protection against erosion. Reduction of the berm height at Ōwhiro Bay is very similar to beach push-ups, moving beach material up/down the beach slope. Even so, resource consent will be required to get permission to undertake this kind of beach management.

6.4 Dune Planting Stabilisation

Widening the beach to create a buffer zone to reduce over-topping through dune stabilisation with native dune species has proven successful along other parts of the southern coast of



Wellington. For example, dune planting has significantly increased the width of the dune buffer zone at Lyall Bay (Mead and Phillips, 2016), and provided increased resilience to erosion⁶ (Figure 6.6). Similar creation of a buffer zone has also been achieved at Island Bay, however, the mobile shingle beach material at Ōwhiro Bay is not conducive the propagation of native dune species (Figure 6.7). In addition, this method to reduce over-topping could not be applied in combination with berm height reduction, it would be either one or the other.



Figure 6.6. Dune planting has significantly increased the width of the dune buffer zone at Lyall Bay (Mead and Phillips, 2016).



Figure 6.7. Left) Dune stabilization at Island Bay, and Right) the gravel beach at Ōwhiro Bay.

⁶ Regular maintenance is still required at the Surfer's Corner end of Lyall Bay due to the abrupt interface of the airport reclamation built in the 1950's, which reclaimed almost 1/3rd of the bay.



6.5 Protect with Seawalls and Revetments

Seawalls and revetments are also common around the south coast of Wellington (Figure 6.8), and have been present in Ōwhiro Bay since at least the 1930's (Figure 2.7). Re-curved seawalls (top left Figure 6.8) are designed specifically to redirect over-topping discharge back towards the sea, and seawalls and rock revetments can both reduce wave run-up and over-topping discharge.



Figure 6.8. Top Left) The re-curved wall at Island Bay. Both Left and Right) The seawall and revetment along the Esplanade near the Victoria University Coastal Ecology Laboratory.

There is potential for further revetments/seawalls and/or heightening revetments/seawalls to mitigate over-topping in Ōwhiro Bay, although there are some factors that indicate that these structures may not be the best solution. It is noted that the results of the community questionnaire indicated that there was some opposition to seawalls, presumably due to loss of visual amenity (not being able to see the sea/beach) and having a concrete structure between the footpath and the beach having a negative impact both the aesthetics and beach access.

An additional issue is the ramping effect of the shingle berm, which is currently to the level of the footpath where the worst of the over-topping occurs on the eastern side of the bay (Figure



6.9). This indicates that should the seawalls be heightened in these areas, there is the potential for the shingle slope to accumulate to the top of the new seawall, and only a relatively small reduction in over-topping discharge will be gained due to waves still propagating up the ramp. This could be addressed by maintaining a reduced berm against the seawall (i.e., Section 6.3), which has the potential to provide a successful mitigation method without the addition of a seawall. The same effect could also occur with the establishment of revetments, however, the placement of revetments would also negate the option to maintain a reduced berm height because of the potential to undermine the revetment toe and cause failure.



Figure 6.9. The shingle beach is presently almost level with the footpath on the eastern side of the bay where some of the worst over-topping occurred in April 2020.

At this stage, seawalls/revetments are not considered a useful option for reducing over-topping at Ōwhiro Bay, although they may be in the long term. An area of the bay that is an exception to this is the at the carpark in the centre of the beach, which is relatively set back from the high tide mark, has a wide area between the road and the high tide, is of relatively high elevation (>4 m above mean sea level Figure 2.5), and already has some rock revetment protection (bottom left image Figure 2.2). Rocks along the seaward edge of the carpark were found to be 700-800 mm diameter during the site visit. To determine the design size/weight of armour units at the site, depth-limited wave heights at the beach were considered (Figure 2.6), as well as the wave heights at the beach captured on a video of the 15 April 2020 event (Figure 6.10), while the LiDAR data and photographs were used to estimate the beach slope.

The size/weight of armour units for revetments are calculated to ensure that they are stable under design conditions (i.e. 100-year return period wave heights during an extreme water level event), with an acceptable failure of <5% of the structures. The US Army Corps of



Engineers' (2006) method for determining stable stone size for particular wave heights relies on the Hudson formula which is expressed as:

$$W = \gamma_r H^3 / K_D (\gamma_r / \gamma_w - 1)^3 cot\theta$$

where,

W = weight of the outer layer armour unit γ_r = unit weight of armour unit H = design wave height K_D = stability coefficient from armour size, shape and material γ_w = unit weight of water θ = angle of structure slope

Where K_D is a stability coefficient taking into account all the other variables. K_D values in the literature are for "no damage" conditions defined so that up to 5% of the armour rock may be displaced. H in the equation being taken as H_{1/10} i.e., the highest 1/10th of all waves. Here "breaking" means wave breaking directly onto the armour rocks. K_D levels of 2 are recommended for angular rock armour under breaking waves, and 3-4 where waves are surging (e.g. in a marina).

For this site, basalt rock and a K_D value of 2 was applied to the Hudson formula. This resulted in a recommended rock size with a nominal diameter (D₅₀) of 0.9 m; a mix of rocks ranging from 0.7 to 1.1 m are considered suitable for the site.



Figure 6.10. Waves at the beach during the 15 April 2020 extreme event.



The existing rock in front of the carpark falls within the calculated rock size/weight for the site, although these calculations are considered preliminary and a more accurate assessment should be undertaken to better determine the beach slope, potential wave height at the beach and the type of rock to be used (the density of the rock determines the size/weight required), and to develop drawings and specifications. To reduce wave run-up onto the road and threatening properties during extreme events, approximately 120 m of rock revetment can be placed along the top of the beach, which includes strengthening some 40 m of rocks already present on the western side of the beach (Figure 6.11). Access through the revetment would be in the form of angled gaps, much the same as angled beach access points to reduce the loss of sand.



Figure 6.11. Potential rock revetment for Ōwhiro Bay to reduce wave run-up onto the road and threatening properties during extreme events.

6.6 Creation of Buffers

As noted in Section 6.4 above, even if the mobile shingle beach were to be conducive to the establishment of a native planted dune buffer zone, it could not be done in conjunction with reduction of the berm against the seawalls. However, creation of buffer zones using coastal



plants (e.g. harakeke, taupata, mingimingi, etc.) planted between the existing seawalls and setback into the foreshore can feasibly increase resilience to over-topping discharge and work in combination with berm grading. Similar buffer zones are present along The Esplanade at Oriental Bay (Figure 6.12), although a lower wall/planting above a graded berm could be applied at Ōwhiro Bay to reduce any impact on views across the bay (Figure 6.13).



Figure 6.12. A buffer zone of coastal plants along The Esplanade. At Ōwhiro Bay it is envisaged that there would be a lower wall/planting above a graded berm as to reduce any impact on views across the bay.





Figure 6.13. Potential planted buffer zone above graded berm to reduce/prevent extreme over-topping.

As noted above, Ōwhiro Bay is constrained by seawalls, roads and footpaths, and so there is a need to create space to create buffer zones (e.g. the footpath has been replaced by coastal plants in Figure 6.13).

6.7 Managed Advance/Buy Time – Offshore Structures

A potential solution to reduce wave run-up, set-up and over-topping in Ōwhiro Bay is the construction of offshore submerged breakwaters (e.g. Figure 6.14). As noted in Section 4, wave set-up is one of the components that leads to extreme over-topping, which increases with increasing wave period. An aspect of offshore submerged breakwaters is that because the waves are breaking on the offshore structure (natural or manmade), there is set-up at the breakpoint, and set-down at the beach in the lee of the structure (e.g. Black and Mead, 2003; Ranasinghe *et al.*, 2006). Utilising both the breaking of waves offshore to decrease the wave height in the bay, as well as wave set-down at the beach has the potential to lead to decreased water level and wave height in the bay; i.e. could buy some time by turning back SLR by several decades.





Figure 6.14. The submerged reef at Oriental Bay is designed to maintain beach sand along the eastern part of the beach through wave rotation (Mead and Black, 2001). (https://satellites.pro/New_Zealand_map#-41.290467,174.795637,19).

At present, it is unknown how effective this approach would be. For example, waves were breaking before entering \bar{O} whiro Bay on 15 April 2020 (Figure 6.15). As can be seen in Figure 2.6, the entrance to \bar{O} whiro Bay is relatively shallow, and so with the application of the rule of thumb depth to wave height at breaking ratio of 0.78, a 6.7 m wave (i.e., the peak significant wave height) will break in 8.6 m of water, with the largest waves of the 15 April event likely breaking in water depths of ~15 m. Therefore the location of submerged structures within the surf zone needs to be considered (both due to the volume/cost and because the waves will have already broken).



Figure 6.15. Waves breaking before entering Ōwhiro Bay on 15 April 2020. As can be seen in Figure 2.6, the entrance to Ōwhiro Bay is relatively shallow, and so with the application of the rule of thumb depth to wave height at breaking ratio of 0.78, a 6.7 m wave (i.e., the peak significant wave height) will break in 8.6 m of water, with the largest waves of the 15 April event likely breaking in water depths of ~15 m.



To determine whether structural intervention to reduce wave height in the bay and create wave set-down at the beach is feasible, in depth investigations are required (e.g. field data collection and numerical modelling). In addition, marine construction within the Marine Reserve would need to be considered.

Similar to lowering water levels within th bay during extreme events, increasing the level of the land/road around the perimeter of the bay is an option which is being seriously looked at in some Pacific Island nations. This is a long term solution that would at present be a very unlikely option – unlike some Pacific Island nations that have nowhere to retreat to, New Zealand has an abundance of high ground.

6.8 Hybrid Solutions – Management and Forecasting and Structures

Hybrid solutions are a form of nature based solutions that combine structural engineering with natural features (e.g. marsh–levee systems; dune–seawall systems; mangrove-revetment systems) (Pontee *et al.*, 2016). At Ōwhiro Bay, hybrid solutions that incorporate the following aspects have the potential to reduce and/or prevent over-topping during extreme events, as well as to be prepared in advance of them:

- 1. Monitor
- 2. Reduction of Berm
- 3. Revetments
- 4. Buffer Zones/Coastal Vegetation
- 5. Knowing What's Coming Preparedness by informing the forecasting system with the knowledge gained by monitoring.

6.9 Retreat

SLR will continue beyond 2100, the height/extent of which is unknown, and similar to the rate at which SLR will occur, this is partly due to how humans react with respect to reducing CO₂ emissions, with several larger scale uncertainties such as land-based ice. This means that retreat from Ōwhiro Bay will be required in the future, although through continued monitoring and adaptive management of measures to combat over-topping, it is expected that the aim to safely live in the bay in the decades to come can be achieved.



7 Recommendations

The following recommendations are directed at short (now), medium (in the next decade), and future (50 years and beyond) options to reduce/prevent over-topping during extreme wave events in Ōwhiro Bay.

7.1 Short Term Management

In the short term, the application of 'no regrets' options is recommended, that is, options that are relatively low cost and do not require large scale construction and/or permanent changes to Ōwhiro Bay.

7.1.1 Monitoring System

A monitoring system should be put in as soon as possible in order to develop an understanding of the dynamics of the beach system, over-topping events and any management options that are applied.

Monitoring comes in many forms, with more sophisticated and cost-effective methodologies being developed in recent years. Given the kind of information that requires monitoring at Ōwhiro Bay (i.e., over-topping events, movement of shingle around the beach, efficacy of options to mitigate the over-topping, etc), remote video monitoring is likely the most efficient and cost-effective methodology.

Ōwhiro Bay is well suited to remote video monitoring due to the elevated topography, and there are several potential powered sites on the eastern side of the bay, as well as the option for a remote system on the top hill country on the western side of the bay. The type of system and its operating capacity is provided in Appendix C.

7.1.2 Beach Grading

Mechanically removing the shingle ramp from in front of the seawalls where over-topping occurs and redistributing the material lower down the beach has the potential to reduce the impacts of over-topping at Owhiro Bay, and could become an important component of the beach management options – anecdotal evidence indicates that it was successful in the past. The monitoring system will be an important aspect of this option in order to determine its efficacy, how the beach responds to grading (i.e. movement of shingle around the beach, conditions that lead to the return of the shingle ramp, locations of over-topping, etc.).



As noted in Section 6.3, beach push-ups are used around New Zealand to provide increased coastal protection against erosion. Reduction of the berm height at Ōwhiro Bay is very similar to beach push-ups, moving beach material up/down the beach slope. Even so, resource consent will be required to get permission to undertake this kind of beach management, which will require an assessment of environmental effects, including investigations into the designs of the existing seawalls (i.e. depth and stability of the toe of the structures) and how these works impact on the marine reserve.

7.1.3 Improvement of Forecast/Warning System

In order to provide confident forecasts to allow Ōwhiro Bay residents to prepare for extreme over-topping events, a better understanding of the combination of metocean parameters that lead to extreme over-topping events is required. A critical component of developing a robust warning strategy is monitoring to determine the extent, locations, and other factors associated with over-topping events, which can then be related back to the metocean parameters; e.g., as done in Section 4 to consider the 15th April 2020 extreme event. These parameters can be catalogued so that when the forecast system identifies the combination of a set of parameters that have historically led to an over-topping event, an appropriate warning can be issued. As the database of known over-topping events increases, so will the efficacy of the warning system.

7.2 Medium Term Management

Medium term management options over the coming decade can be considered for implementation based on the success (or not) of the short term options above, which is also linked to monitoring. For example, beach grading may effectively significantly reduce or prevent over-topping and mean that buffer zones are not required. Another scenario may be that the beach grading is successful for the areas in front of the seawalls, however, run-up and over-topping still occurs along the carpark area meaning the revetment requires upgrading and extending. Medium term options can be integrated with short term options to develop hybrid solutions (Section 6.8).

7.2.1 Revetment Construction

As noted in Section 6.5, at this stage, seawalls/revetments are not considered a useful option for reducing over-topping at Ōwhiro Bay (although they may be in the long term), with the exception of the carpark in the centre of the beach, which is relatively set back from the high



tide mark. This area is relatively wide between the road and the high tide, is relatively high (>4 m above mean sea level), and already has some rock revetment protection.

Preliminary estimates of rock-size for revetment along this part of the beach indicate a nominal diameter (D₅₀) of 0.9 m (rocks of 0.7 to 1.1 m are considered suitable for the site). A more accurate assessment should be undertaken to better determine the beach slope, potential wave height at the beach and the type of rock to be used (the density of the rock determines the size/weight required), and to develop drawings and specifications.

To reduce wave run-up onto the road and threatening properties during extreme events, approximately 120 m of rock revetment can be placed along the top of the beach, which includes strengthening some 40 m of rocks already present on the western side of the beach. Access through the revetment would be in the form of angled gaps, much the same as angled beach access points to reduce the loss of sand.

7.2.2 Buffer Zones/Coastal Vegetation

Should beach grading be only partially effective at reducing over-topping, the creation of buffer zones using coastal vegetation (potentially interspersed with 900 mm rocks for added over-topping reduction) could be applied along the sections where required. Ōwhiro Bay is constrained by seawalls, roads and footpaths, and so there is a need to create space to implement these 'living barriers', such as replacement of the footpath with coastal plants.

7.3 Long Term Management

Long term planning should consider the potential to reduce wave energy prior to reaching the beach and reducing wave setup in order to reduce over-topping using structures such as submerged breakwaters. An aspect of offshore submerged breakwaters is that because the waves are breaking on the offshore structure (natural or manmade), there is set-up at the breakpoint, and set-down at the beach in the lee of the structure. Utilising both the breaking of waves offshore to decrease the wave height in the bay, as well as wave set-down at the beach, has the potential to lead to decreased water level and wave height in the bay; i.e. it could buy some time by turning back SLR by several decades.

To determine whether structural intervention to reduce wave height in the bay and create wave set-down at the beach is feasible, in depth investigations are required (e.g. field data collection and numerical modelling). In addition, marine construction within the Marine Reserve would need to be considered.



Other options that can also be considered in the longer term include increasing the height of seawalls around the perimeter of the bay (and continuing beach grading to prevent ramping against the seawalls), increasing the level of the land/road around the bay and managed retreat.

Figure 7.1 summarises the coastal engineering options to reduce or prevent over-topping during extreme events at Ōwhiro Bay. The immediate recommendations include establishing a monitoring system (red star) and beach grading. Medium term management could include the upgrade and extension of the rock revetment and the creation of buffer zones. In the longer term, there is potential that submerged breakwaters could be beneficial, although the efficacy, size and location of these is presently unknown.





Figure 7.1. Options to reduce or prevent over-topping at Ōwhiro Bay. The immediate recommendations include establishing a monitoring system (red star) and beach grading (orange lines). Medium term management could include upgrade and extension of the rock revetment (blue line) and the creation of buffer zones (green line). In the longer term, there is potential that submerged breakwaters could be beneficial, although the efficacy, size and location of these is presently unknown.



References

- Atkin, E., T. Hume, S. Mead, K. Bryan, and J. Waiti, (2017). Remote Sensing, Classification and Management Guidelines for Surf Breaks of National and Regional Significance.
 Proceedings of the 23th Australasian Coasts and Ports Conference, Cairns, Australia, 21-23 June 2017.
- Black and Mead, (2003). Numerical Prediction of Salient Formation in the Lee of Offshore Reefs. *Proceedings of the 3rd International Surfing Reef Symposium, Raglan*, New Zealand, June 22-25, 2003. Pp 196-218.
- Carter, L and Lewis, K., (1995). Variability of Modern Sand Cover on a tide and storm driven inner shelf, south Wellington, New Zealand. *New Zealand Journal of Geology and Geophysics*, 38:451-470.
- Eurotop, 2007. http://www.overtopping-manual.com/manual.html.
- Harrison, S., & Bryan, K. R. (2014). Video observations of sandbar movement at the Raglan Bar. In *Proceedings of Technical Groups, New Zealand Coastal Society 22nd Annual Conference.* (pp. 70). New Zealand Coastal Society.
- Kennedy, D. M., & Beban, J. G. (2005). Shore platform morphology on a rapidly uplifting coast,
 Wellington, New Zealand. *Earth Surface Processes and Landforms, 30(7), 823–*832. doi:10.1002/esp.1192
- Mead, S. T., (2020.) *Manu Bay Breakwater: Science and Monitoring*. Prepared for Waikato District Council, April 2020.
- Mead S. T., and K. P. Black, 2001. Wave Rotation for Coastal Protection. *Proceedings of the Australasian Coasts & Ports Conference*, Gold Coast, Queensland, Australia, 25-28 September 2001.
- Mead, S. T., and D. J. Phillips, (2016). *Lyall Bay, Wellington: Coastal Remediation*. Prepared for Wellington City Council, June 2016.
- Ministry for the Environment, (2017). The Coastal Hazards and Climate Change: Guidance for Local Government. ISBN: 978-1-98-852535-8
- Pillans, B & Huber, P. (1995). Interpreting co-seismic deformation using Holocene coastal deposits, Wellington, New Zealand. Quaternary International 26: 87–95.
- Pontee, N., Siddharth, N., Beck, M. W., & Hosking, A. H. (2016). Nature-based solutions: Lessons from around the world. *Maritime Engineering*, Vol 169, Issue MA1.



- Ranasinghe, R., Turner, I.L. and Symonds, G (2006). Shoreline response to multi-functional artificial surfing reefs: A numerical and physical modelling study. *Coastal Engineering* 53: 589-611
- USACE, (2006). *Coastal Engineering Manual*. Washington, D.C.: U.S. Army Corps of Engineers.
- van Gent, Marcel RA, *et al.*, (2007). Neural network modelling of wave overtopping at coastal structures. *Coastal Engineering* 54.8 (2007): 586-593.



Appendix A – Historical Imagery































Appendix B – Ōwhiro Bay Residents Association Coastal Survey



Appendix C – Remote Video Monitoring System